



# Wireless Hygrometer

Item No. 95907

## FEATURES:

1. Touchscreen display shows temperature, humidity, and max/min values at the base and remote units.
2. Temperature can be displayed in Fahrenheit or Celsius.
3. Maximum and minimum value can be easily reset.
4. Maximum and minimum value can be set to automatically reset every 24 hours.
5. Includes magnets, quick-connect bracket and screws for installing on wall.
6. Compatible with Hornady Square-Lok™ system.

## OPERATION:

Begin by removing the battery cover from the base and remote unit and installing new AAA batteries into both the base and remote units. It may take up to one minute for the base and remote to connect after installing batteries.

### A. REMOTE / BASE Button

- Press and release to toggle between displaying the remote readings and base readings.
- Press and hold to manually initiate pairing between the base and remote.

**NOTE:** Whenever batteries are placed in the base unit, the base unit automatically initiates the connection process with the remote, but it must wait until the remote broadcasts a signal to establish a connection. If replacing the batteries in just the remote, a manual connection will be needed. It is best to replace the batteries in the base and remote at the same time.

### B. °F / °C Button:

- Press to toggle between displaying temperature in Fahrenheit or Celsius.

### C. ALL TIME/24 HRs:

- Press and release to toggle between ALL TIME and 24 HRs min/max interval.
  - i. ALL TIME: Displays the min/max readings until manually reset.
  - ii. 24 HRs: Displays the min/max readings over a 24 hour period. Automatically resets every 24 hours.
- Hold down this button for 3 seconds to clear the recorded maximum and minimum value.

### D. Signal Icon:

- The icon will blink when first establishing a connection.
- When the base and remote are connected, this icon remains on.
- Icon will blink approximately every 50 seconds when the base and remote update readings.

### E. Comfort Icon:

- Displays general comfort levels based on humidity readings.

**COMF** – A comfortable humidity level is between 30% and 60%  
**WET** – Any humidity level higher than 60%  
**DRY** – Any humidity level less than 30%

DISPLAY BASE




## QUICK CONNECT BRACKET:

The Hygrometer ships with two brackets to allow the Hygrometer to be mounted to vertical surfaces.

To connect the hygrometer to the bracket, place the hygrometer onto the bracket and rotate 90 degrees.

## PROPER CARE:

1. Keep product clean. A buildup of dust could affect the accuracy of the thermometer and hygrometer.
2. Do not drop as it may damage the sensitive electronics.
3. For indoor use only. Keep away from water.
4. Replace batteries when the display begins to dim.
5. The touchscreen is designed to read a soft fingertip.  
**DO NOT** use a fingernail or other hard object as it may damage the screen.



## TROUBLESHOOTING:

If the touchscreen buttons are not working properly, please try the following steps:

1. Clean the screen with rubbing alcohol and a soft cloth.
2. Remove the batteries to reboot hygrometer.

## SPECIFICATIONS:

1. Temperature range: -10 ~50° C (14-122° F)
2. Humidity range: 10% ~99%RH
3. Maximum read distance: 100 feet unobstructed
4. Measurement period: 50 second intervals
5. Power supply: Four AAA batteries total (not included).  
*Base Display requires two batteries and Remote Sensor requires two batteries.*
6. Dimensions:

### Base Display

76 x 63 x 15mm (3.0" x 2.5" x 0.6") | Net weight: 4.0 oz (113.4g)

### Remote Sensor:

72 x 72 x 25mm (2.8" x 2.8" x 1.0") | Net weight: 1.6 oz (45.4g)

## INCLUDED IN THE BOX:

- |                      |                |
|----------------------|----------------|
| a. Base Display Unit | d. User manual |
| b. Remote Unit       | e. Wood Screws |
| c. Twist-Lock Mount  |                |

**Hornady Security® electronic components are covered by a one-year warranty from the date of purchase. See [Hornady.com](http://Hornady.com) for details.**

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

P.O. Box 1848, Grand Island, Nebraska 68802-1848  
308-382-1390 • 800-338-3220 • Fax: 308-382-5761

[Hornady.com/contact](http://Hornady.com/contact)